

# TROUBLESHOOTING

## Xenon Lamps >450W lamps to include XBO® and Xstage types

There are a number of reasons why a lamp may not give satisfactory performance. The following may help you to locate and correct the more common problems that can cause failure, and ensure longer life for the replacement lamp.

	Symptom	Fault	Remedy
1. 	Connector base discolored	Connector base overheated above 230°C due to: <ul style="list-style-type: none"> <li>- Faulty electrical connection</li> <li>- Improper lamp cooling</li> <li>- Improper lamp current</li> <li>- Optical system out of alignment</li> </ul>	Check electrical connections: <ul style="list-style-type: none"> <li>- Tighten or replace</li> <li>- Check operating current</li> <li>- Check cooling system (forced or convection)</li> <li>- Check optical adjustment</li> </ul>
2. 	Blackening or clouding of quartz bulb	Operational air infiltration due to: <ul style="list-style-type: none"> <li>- Crack in graded seal typically caused by overheated connector base (maximum temperature of 230°C exceeded).</li> </ul>	Ensure proper operational current. Check electrical connections: <ul style="list-style-type: none"> <li>- Tighten or replace</li> <li>- Check cooling system</li> <li>- Check optical adjustment</li> <li>- Check operation current</li> </ul>
3. 	Severe cathode electrode damage, grey/brown deposits on quartz envelope	Reversed polarity due to: <ul style="list-style-type: none"> <li>- Electrical connection incorrectly applied to lamp</li> <li>- Incorrect wiring</li> </ul>	Check polarity, correct connections if necessary. <ul style="list-style-type: none"> <li>- Vertical lamp operation only with anode electrode (+ connection) up</li> </ul>
4. 	Abnormal anode electrode deterioration, blackening of lamp	Arc instability due to: <ul style="list-style-type: none"> <li>- Lamp operated outside current control range</li> <li>- Lamp operated with poor quality operational current</li> <li>- Improper magnetic stabilization</li> <li>- Improper forced cooling</li> </ul>	Check correct current setting <ul style="list-style-type: none"> <li>- Check magnetic stabilization</li> <li>- Ensure proper quality current</li> <li>- Ensure forced cooling as required by OSRAM</li> </ul>
5. 	Deposits on anode face	Rectifier/power supply defect: <ul style="list-style-type: none"> <li>- Inrush current limit exceeded</li> <li>- High current ripple</li> </ul>	Check <ul style="list-style-type: none"> <li>- Rectifier/power supply</li> <li>- Inrush current</li> <li>- Current ripple</li> </ul>

Display/Optic Laboratory  
 OSRAM SYLVANIA  
 c/o Danzas AEI  
 8470 Gran Vista Street  
 El Paso, TX 79907  
 Phone: 915-775-2939  
 Fax: 915-775-2924

Ordering Code: FO179 R2

February 2008

SEE THE WORLD IN A NEW LIGHT

